


INSTRUCTIONS FOR REPAIRING MESH CONVEYOR BELTS

If your oven belt is damaged, it may be repaired, depending on the degree of damage.

Cuts or Tears

1. Trim away all loose yarn at the area to be repaired.
2. Take tension off the belt until it is slack.
3. Using the lacing provided, weave across the area to be repaired as shown in the diagram at right and tie off the ends.
4. If a patch is required, make sure the cut piece of mesh extends beyond the damaged area by at least 3". Weave on patch per diagram, using lacing tape provided.



Larger pieces of belting are available. Please call Graphic Parts International, Inc. for the cost of a newly manufactured belt for your machine.

CALL TOLL-FREE: 800.444.PART



A Division of The A.W.T. World Trade Group
4321 N. Knox Ave., Chicago IL 60641 USA
773.725.4900 • Fax: 773.777.0909

REPLACEMENT PARTS AND REMANUFACTURING SERVICES FOR SCREEN PRINTING EQUIPMENT

parts@gpiparts.com • www.gpiparts.com